## **Occidental Chemical Corporation**

September 30, 1983 FilingifAction

Co: Larrach Baker

Liriet reply

Response due

1927/83

Ms. Jacqueline Schaefer Regional Administrator USEPA - Region II 26 Federal Plaza New York, NY 10278

> Occidental Petroleum Corporation (OCC) Facility No. NYD 000 831 644 Application For Revision to Interim Status Permit

Dear Ms. Schaefer:

Pursuant to the requirements of 40 CFR Section 270.72 (c), OCC is applying for a revised Interim Status Permit. A revised Part A permit application reflecting the requested changes for the subject facility is attached. This change is being requested to prevent an emergency situation from developing at Hyde Park, as described below.

The present storage facility is a surface impoundment which stores aqueous and non-aqueous leachate from the Hyde Park Landfill for subsequent shipment to appropriate disposal facilities. The surface impoundment serves as a separator for the two liquid phases, and the upper aqueous phase is regularly removed and shipped to OCC's Niagara plant for treatment in a facility which employs activated carbon.

The heavier organic phase is slowly building up in the bottom of the impoundment. A plan for disposing of this organic waste at the new SCA incinerator in Chicago was submitted to the USEPA and the State of New York (EPA/State) on June 24, 1983. That plan detailed a plan for incineration and emphasized the emergency which would result if approval was delayed. response to this submission was received by OCC on August 26, 1983 requesting additional information and risk assessments, and OCC and SCA are presently working on a reply to the above agency's requests. While the review of the organic waste disposal plan continues, the leachate continues to be collected and stored in an impoundment which is slowly reaching its capacity.

The present impoundment has a total capacity of 280,000 gal. and. allowing for the minimum allowable freeboard of 24 inches, the safe working capacity is 187,000 gal. The organics are being collected at a rate of 4,000 gal/month, and the aqueous leachate is collected at an average rate of 7500 gal/day which ranges from 4,000 gal/day in the fall to 14,000 gal/day during the early spring thaw. Although the aqueous leachate is regularly removed for treatment, the organics layer is slowly building up and reducing the working volume for aqueous phase collection and separation.



The current and projected lagoon inventories are as follows:

T. Egypton (	Organics Inventory	Volume Available For Aqueous Storage
Present (9-1-83)	142,000 gal.	45,000 gal.
Forecast (2-1-84)	162,000 gal.	25,000 gal.

Thus by next spring, less than a two day storage capacity for aqueous leachate will be available, and the rapid inventory turnover can be expected to interfere with the liquid separating ability of the impoundment.

While we still believe that approval of the plan to incinerate the organics is the best solution, to prevent an emergency situation from arising and possibly halting the leachate collection operation, a plan for installing four (4) tanks to 10,000 gal. capacity each (total 40,000 gal.) has been submitted to EPA/State. This will increase the storage capacity for leachate and delay the advent of an emergency situation, even if none of the organics are removed from the site

The final details of the temporary storage plan will be submitted to EPA/State, but a revised interim status permit must be obtained before the tanks can be installed. Because of the need to move and compact the clay before freezing weather, OCC will proceed with the installation of the clay dike at OCC's risk. The installation of the tanks and piping will be deferred until all necessary approvals are obtained.

Your prompt attention to this request would be appreciated to permit installation of the tanks before freezing weather sets in.

Please call me at (716) 286-3609 if you have any questions on this application.

Respectfully,

John R. Nichter

Hyde Park Coordinator

John R. Butter

1550eJRN1g

Attachment: Revised Part A

Copies: Joseph Spatola, EPA Region II

Joseph Slack, DEC, Albany Peter Buechi, DEC, Region 9

in an electric percent of the type, may	s/inch).				-		d OMB No. 15	8-R01	75		
				ATION	1. E	PA I.D. NU	MBER 1	4		Por of	
VEPA	Consoli	deteo	Permits P	rogram	F	NY D C	0 0 83	1 6	4	4	
GENERAL (Read	LABELITEMS GENERAL INSTRUC									13 14 1	
I. EPA I.D. NUMBER	11	1	11,	11111	111	a preprints	d label has be gnated space. F	en pr	ovide	d, affix	
	11.	1,	11,	11111	\ ati	on carefully	y; if any of it	is inc	orrec	t. cross	
IL FACILITY WAME	11,	1,	111	11111	1 80	propriate fi	II-in area belo	W. A	so. H	any of	
FACILITY	111	11	111	11111	\ let	t of the la	abel space list	nt (the area to ti			
MAILING ADDRESS PLEASE	PLACE	LĄ	BET IN	THIS SPACE	/ pr	oper fill-in	ppear), please a area(s) below	N. If	the	label is	
LLLLX	111	1	11		1 120	ms 1, III,	V, and VI (e	xcept	VI-E	3 which	
FACILITY	111	1	11	11111.	lite	ms if no la	pleted regardi	provid	ed. F	Refer to	
"LOCATION	11	1	11	11111	tic	ons and for	ons for detail the legal au				
	11	-	11		M	nich this dat	a is collected.	l here	Constants.		
. POLLUTANT CHARACTERISTICS	JAN JA							45.0			
INSTRUCTIONS: Complete A through J to determ questions, you must submit this form and the supp	nine wheth lemental fo	er yo irm li	u need to	submit any permit applic parenthesis following the	ation for auestion	ms to the El . Mark "X"	in the box in t	ver by	ird co	o sny	
if the supplemental form is attached, if you answer	"no" to e	ach q	uestion, y	ou need not submit any of	f these fo	rms. You ma	ay answer "no"	if yo	ur ac	tivity	
is excluded from permit requirements; see Section C	of the instr		ns. See als	o, Section D of the instruc	tions for	definitions	01 8010-19080	Cerms	MAR	K 'X'	
SPECIFIC QUESTIONS	YES		PORM		IC QUE			725	NO.	FORM	
A. Is this facility a publicly owned treatment which results in a discharge to waters of the		v		B. Does or will this fac include a concentre					х		
(FORM 2A)		X		aquatic animal prod discharge to waters o	uction fa	cility which	results in a	10	20	21	
. Is this a facility which currently results in disch to waters of the U.S. other than those describ		X		D. Is this a proposed fa	cility (ot	her than the	ose described		X	his s	
A or B above? (FORM 2C)	22	12		waters of the U.S.? (	FORM 2	)		29	26	27	
Does or will this facility treat, store, or dispo		F. Do you or will you inject at this facility industrial or municipal effluent below the lowermost stratum con-									
hazardous wastes? (FORM 3)	X	29		taining, within one underground sources				31	X	33	
<ul> <li>Do you or will you inject at this facility any proc water or other fluids which are brought to the st</li> </ul>	duced		acalesa.	H. Do you or will you				10	1.8	(T) (apa	
in connection with conventional oil or natural ga duction, inject fluids used for enhanced recove	s pro-	X			such as mining of sulfur by the Frasch ion mining of minerals, in situ combus-						
oil or natural gas, or inject fluids for storage of hydrocarbons? (FORM 4)	liquid		A STATE	tion of fossil fuel, of (FORM 4)	or recover	y of geothe	rmal energy?		34	10	
Is this facility a proposed stationary source whose of the 28 industrial categories listed in the	ich is	30	16	J. Is this facility a pro NOT one of the 28	oposed st	ationary so	urce which is	-			
structions and which will potentially emit 100	tons	x		instructions and wh	ich will p	otentially e	mit 250 tons		x		
per year of any air pollutant regulated unde Clean Air Act and may affect or be located	in an			Air Act and may af							
attainment area? (FORM 5)  I. NAME OF FACILITY			1633-251	erea? (FORM 5)			PIER S	43	44		
SKIPO C CI D E NT A L C H	E M IC	A	L C	O RP O RA T				'		Carti	
16 - 29 30	1000000	A STY	THE MARINE		1865.93	September	र सम्बद्धाः स	***	42	300	
A. NAME & TITLE	ast, first.	title			D. PH	ONE (area c	ode & no.)	-	-	-	
JUSZKIEWICZ JOS	EP H	s	1- 1- 1-	RVISOR	716	278	747 7	27	gr-	7534	
16	186-19	STEE	Harman are		6 - 40 25 US	49 10	92 93	Carl St	None P	district of	
FACILITY MAILING ADDRESS						W6.75		200	1		
47 th & B U F FA L O A V			L L	FITTE	a jet som s	all wilder				Have	
47 th & B U F FA L U A V					ene men	THE SHOP BY			2	No.	
B. CITY OR TOWN			1_1 1		CODE						
N IA G AR A F A L LS N	EW	0	RK	N Y 1 4	303				7.55		
FACILITY LOCATION	MAGE				0.00	Service Control		2 /2	936	741	
A. STREET, ROUTE NO. OR OT	HER SPEC	IFIC	IDENTIF	ER	W 17		ziwajanje			Maria I	
4. 8. 25. H.Y.D.E.P.A.R.K.	BO	ŲL	EV A	R, D	1. 143.16					T ALE	
B. COUNTY NAME				on the day sales of the		10 mg					
N.T.A.C.		50.00	FFF	G 1254 1085		1000				Take.	
N. I. A G A R.A.				D.STATE E. ZIP	CODE	F. COUN	TY CODE				
C. CITY OR TOWN	سن	-	111		F		iown)				
T.O. WN. OF N. I.A. G. A. R. A.		9-7		N Y 1 4	30 .5	12		4 4 4	- 39		
PA Form 3510.1 /6.901				the second second second second second				AULE	_		

CONTINUED FROM THE FRONT				<b>建筑工作的工作</b>
VII. SIC CODES (4-digit, in order of priority)	***	AND THE WAY		Children Control
A. PIRST	THE WALLES MADERA	OF THE WAY THE COURT	B. SECOND	
7 9 9 99 (specify)	A THE THE LINE OF STREET	c (specif)	7	Arta-ta. No.
Nonclassifiable E	stablishment	15 16 - 19		
C. THIRD		c     (specif)	D. FOURTH	
7 ispecijy)	<b>自由有效的</b>	7		
VIII, OPERATOR INFORMATION				Salver Commence
VIII. OPERATOR IN ORDINATION	A. NAME		MANAGER CONTRACTOR	B. Is the name listed in Item VIII-A also the
<u> </u>		The late of the la		owner?
8 O.C. CI.D. ENT A.L. C.H.E.	M IC. AL. C.O.R	PO R. A. TI. ON	·	YES NO
C. STATUS OF OPERATOR (Enter the appr		r box; if "Other", specify		(area code & no.)
F = FEDERAL M = PUBLIC (other than f S = STATE O = OTHER (specify) P = PRIVATE	rederal or state) P (st	pecify)	A 7' 1'6	34 0 75 3 5
E. STREET OF				and the first of the second
	,V.D			•
F. CITY OR TOW	WHILE THE RESTAUR	G.STATE H. ZII	CODE IX. INDIAN LAND	· 生态。
BHOUSTON	and a second parts of	T X 7 7	056 Is the facility locate	
BHOUSTON	AND PROPERTY OF THE PARTY.		USO YES	Ď NO
19 16 16 16 16 16 16 16 16 16 16 16 16 16	transfer to the control of the	40 41 42 47	Secretary desired the second state	
X. EXISTING ENVIRONMENTAL PERMITS		from Proposed Sources)		
A. NPDES (Discharges to Surface Water)	C T I I I I			
9 N , , , , , , , , , , , , , , , , , ,	9 P	and the second second second		
B. UIC (Underground Injection of Fluids)	19 15 17 18 E. OTHE	(specify)	Light State of the	A SURE LIVER AND CAMBORS
	271111		(specify)	A STATE OF THE PARTY OF THE PAR
9 U	15 16 17 18	• • • • • • • • • • • • • • • • • • • •	30	
C. RCRA (Hazardous Wastes)		(specify)	purities and the subject of	Complete Section 18
9 R	9	A SOURCE SEE STREET	(specify)	a the word Assets
	15 16 17 10	and the second section of the section of	TO PERSONAL PROPERTY OF THE STATE OF THE STA	and the state of the state of the state of
Attach to this application a topographic may the outline of the facility, the location of e treatment, storage, or disposal facilities, and water bodies in the map area. See instruction  XII. NATURE OF BUSINESS (provide a brief described in the collect and non-aqueous phase or containing numerous chloment at the site, which liquid collected, is slow of a plan to dispose of surface impoundment (280,00 with a total capacity of	dech of its existing and parties for precise requirements for precise requirements for precise requirements. These ganics. These rinated organiserves to storwly filling up this organic word of should be	roposed intake and dicts fluids underground is.  nd shipment of materials are chemicals. e and separate with the ore aste, the lie	of contaminated re leached from The existing the the aqueous aganic phase. Pour guid storage capage and storage capage capage and storage capage capage in the storage capage capage in the storage capage in the storage capage capag	its hazardous waste s and other surface groundwater a landfill surface impourand non-aqueous and ing approvations of the
I certify under penalty of law that I have p attachments and that, based on my inquir application, I believe that the information of false information, including the possibility of	y of those persons imn is true, accurate and con	nediately responsible f nplete. I am aware the	ior obtaining the informat at there are significant per	ion contained in the salties for submitting
A. NAME & OFFICIAL TITLE (type or print)	B. SIGNAT	URE	Contract Contract	DATE SIGNED
Norman Alpert - Vice Pre Occidental Chemical Cor		rman alf	ent 10	Jeh 3, 1983
COMMENTS FOR OFFICIAL USE ONLY C C 15 16 EPA Form 3510-1 (6-80) REVERSE				
EPA Form 3510-1 (6-80) REVERSE				

					e in the un paced for e				rs/inch).							Form Approx	red OMB	No. 1!	58-S8I	0004	MAR
HAZARDOUS WASTE PERMIT APPLICATION  Consolidated Permits Program  (This information is required under Section 3005 of RCRA.)							TION	I. EPA I.D. 5 N Y D	NUMBE	-		6 4	1 = 1/A								
FO	)R	01		NI	USE ON	EIVED	1							1			resista		<b>STE</b>		
		73		24		29									A SUPPLIES AND A SUPP	a Miles					ro- pr
11.	Fì	RS	T C	)R R	EVISED	APPL	CAT	ION				13 1	1900		A Section 1				26	5-7	
EP.	A I.	D.	Nun	nber	in Item I a	bove.	rst app	ilication and	you airead	y know your	tacilit	y's	ethe	r th	his is the first ap D. Number, or it	plication you this is a revise	are submi d applica	tting t	or yo	ur fac	cility or a
A.						LITY (S	see ins		definition	ne appropriate of "existing"						2.NEW FA	CILITY (				low.)
8 15	I	73	74	75	76 77 78	(use	the box	es to the lef	t)	OVIDE THE ATE CONST	RUCT	101	r., m CO	0., MM	& day) IENCED	VR. MO.	DAY 1	(yr.,	MO.,	THE day	DATE ) OPER OR IS DEGIN
В.	RE	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	SEI	CIL	PLICATI	ION (p	M ST	"X" below NTUS	and comp	lete Item I ab	ove)					2. FACILIT	Y HAS	RCR	A PE	RMIT	
Ш	PI	RO	CE:	SSES	- CODI	ES AN	D DE	SIGN CAP	ACITIES								1		W. W.		STATE OF
в.	PRO	orit OC AN UN	ESS MOU	DES NT -	IGN CAPA - Enter the	ACITY amour	- For	a, enter the concept of the concept	tered in co	provided on lumn A enter	the fo	if a orm apa	(Iten	cess n // of t	Cine (III) beautiful (III)	at is not inclu	ded in the	list o	f code	s belo	ow, then
				ROC			PRO- CESS CODE	APPROPE MEASUR	RIATE UN E FOR PR	ITS OF	usea.			PR	OCESS	PRO- CESS CODE	MEAS		FOR	PRO	CESS
W	AST	K	PIL	E	rrel, drum UNDMEN		S01 S02 S03	GALLONS GALLONS CUBIC YA CUBIC ME GALLONS	OR LITE OR LITE RDS OR TERS	RS RS	SU	NK RF		IMI	POUNDMENT	HE WEST	GALLO LITERS GALLO LITERS	NS PER	ER DAY	AY 0	R
LZ	IN	CT	ION	WEL			D79 D80	GALLONS ACRE-FEE would cove depth of on HECTARE	T (the volu r one acre ne foot) OF	ime that	OTHER (Use for physical, chemical, thermal or biological treatment processes not occurring in tanks.				HOU ER D	R	OR				
00	E	N	DIS	POS	NNDWEN. YF LION	T	D81 D82 D83	ACRES OR GALLONS LITERS PE GALLONS	PER DAY	OR	ato	rs.	Desc	ribe	idments or inci- the processes ided; Item III-0	in 2.)					
U	VIT	0	FMI	EASL	JRE		UNIT MEAS COL	URE	UNITO	F MEASURE				ME	NIT OF ASURE	UNIT OF M	FASIIRE			ME	NIT OF ASURE
CL	BI	RS C N	YAR MET NS P	ERS ER C	DAY	WG ITE		L Y C U Shown in line	TONS P METRIC GALLO LITERS	PER DAY . ER HOUR . TONS PER NS PER HOUR PER HOUR X-1 and X-2 It can burn up	HOU!	R			V D W E	ACRE-FEET HECTARE- ACRES HECTARES	T METER.		:::		A F B
Š C	3				DUP			1/4 5		Can burn up	1020	\ \	Tons	per	nour.	111	11	7	1		11
1 12				41	B. PRO	CESS	DESIG	SN CAPAC	ITY	111	1	$\vdash$		-	P PPO	ESS DESIG	N CARA		1	1	11
NUMBER	Contro	E	list (e)		1-32	I. AMO (speci	UNT		2. UNIT OF MEA SURE (enter code)	FOR OFFICIAL USE ONLY	LINE	100	PR ESS OD om l bove	S E list	1990	. AMOUNT	N CAPA	2.	UNIT F ME A SURE enter code)	. 0	FOR FICIAL USE ONLY
(-1	S	0	2			600	100		G	26 - 32	5	5	0	2		,000		27	G G	29	
(-2	T	0	3			20			E		6	S. S. S.		11.				2			
1	s	0	4		30	0,0	00		G		7				4744	di Nesis					
2	S	0	2			LO,0	00		G		8	0000									
3	s	0	2			10,0	00		G		9					d Parkets					

10,000

10

G

DESCRIPTION OF HAZARDOUS WASTES  PARTICUDE DESIGN CAPACITY.  DESCRIPTION OF HAZARDOUS WASTE NUMBER — Enter the four—Spin number to make the particular describes the characteristic of toxic contaminants of those hazardous wastes.  PARTICUDE DESIGN CAPACITY.  DESCRIPTION OF HAZARDOUS WASTE NUMBER — Enter the four—Spin number to preach lated hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four—digit number to preach lated hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four—digit number to preach lated hazardous wastes.  ESTIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an an ability. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non—listed waste(s)-that will be handled on an an analysis.  PARTICUDE DESIGN CAPACITY.  DISTRIPTION OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriodes are:  ENGLISH UNIT OF MEASURE — CODE METRICUNIT OF MEASURE — CODE METRICU	II. PROCESSES (continued)	A Section of	THE RESIDENCE CONTRACTOR OF THE PERSON OF TH	The state of the s
DESCRIPTION OF HAZARDOUS WASTES  PA HAZARDOUS WASTE NUMBER — Enter the four—digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If handle hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four—digit number/al from 40 CFR, Subpart C that describes the characteristic or toxic contaminants of those hazardous waste.  SETIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an an experiment of the contaminant entered in column A estimate the total annual quantity of all the non—listed waste/al-that will be handled on an an experiment of the contaminant entered in column A estimate the total annual quantity of all the non—listed waste/al-that will be handled on an an experiment of the contaminant entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate are:  ENGLISH UNIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate density of the contaminant entering the context of the required units of measure taking ecount the appropriate density or specific gravity of the waste.  PROCESSES  PROC	SPACE FOR ADDITIONAL PROCESS CODES OR FO	OR DESCRIBING OTH	ER PROCESSES (code "TO4"). FOR EACH PI	ROCESS ENTERED HERE
EPA HAZARDOUS WASTE NUMBER — Enter the four—digit number from 40 CFR, Subpart D for each listed hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four—digit number/s/ from 40 CFR, Subpart C that describes the characteristic and/or the toxic contaminants of those hazardous wastes.  ESTIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an ambasis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non—listed waste/s/-that will be handled on an ambasis. For each characteristic or contaminant.  UNIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate codes are:    ENGLISH UNIT OF MEASURE			2、《政治等任法》,被关于"公共"的	
EPA HAZARDOUS WASTE NUMBER — Enter the four—digit number from 40 CFR, Subpart D for each listed hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four—digit number/s/ from 40 CFR, Subpart C that describes the charact tics and/or the toxic contaminants of those hazardous wastes.  ESTIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an ambasis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non—listed waste/s/-that will be handled on an ambasis. For each characteristic or contaminant.  UNIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate codes are:  ENGLISH UNIT OF MEASURE CODE METRIC UNIT OF MEASURE CODE NOT				
EPA HAZARDOUS WASTE NUMBER — Enter the four—digit number from 40 CFR, Subpart D for each listed hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four—digit number(s) from 40 CFR, Subpart C that describes the charactics and/or the toxic contaminants of those hazardous wastes.  ESTIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an analysis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non—listed waste(s)-that will be handled on an analysis. For each characteristic or contaminant.  UNIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate codes are:  ENGLISH UNIT OF MEASURE CODE METRIC UNIT OF MEASURE CODE  POUNDS. TONS				
PA HAZARDOUS WASTE NUMBER — Enter the four—digit number from 40 CFR, Subpart D for each listed hazardous waste vou will handle. If nandle hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four—digit number/s/ from 40 CFR, Subpart C that describes the charactics and/or the toxic contaminants of those hazardous wastes.  ESTIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an analysis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non—listed waste/s/-that will be handled on an analysis. For each characteristic or contaminant.  JNIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate are:  ENGLISH UNIT OF MEASURE CODE METRIC UNIT OF MEASURE CODE  FOUNDS. — PROCESSES. — Records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking account the appropriate density or specific gravity of the waste.  PROCESSES. — For listed hazardous waste: For each listed hazardous waste entered in column A select the code/s/ from the list of process codes contained in Item to indicate how the wastes: For each characteristic or toxic contaminant.  Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three or described shared on wastes that post that characteristic or toxic contaminant.  Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three or described shared to the space of the code of the process are provided for entering process codes. If more are needed: (1) Enter the first three or described shared to the code of t				
PA HAZARDOUS WASTE NUMBER — Enter the four-digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If sand/or the toxic contaminants of those hazardous wastes.  STIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an aniasis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste/s/. that will be handled on an aniasis. For each characteristic or contaminant.  JINIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate are:  ENGLISH UNIT OF MEASURE — CODE METRIC UNIT OF MEASURE — CODE FOUNDS. — FILLOGRAMS. — METRIC TONS. — METRIC TON				
PA HAZARDOUS WASTE NUMBER — Enter the four-digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If sand/or the toxic contaminants of those hazardous wastes.  STIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an aniasis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste/s/. that will be handled on an aniasis. For each characteristic or contaminant.  JINIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate are:  ENGLISH UNIT OF MEASURE — CODE METRIC UNIT OF MEASURE — CODE FOUNDS. — FILLOGRAMS. — METRIC TONS. — METRIC TON				
PA HAZARDOUS WASTE NUMBER — Enter the four-digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If sand/or the toxic contaminants of those hazardous wastes.  STIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an aniasis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste/s/. that will be handled on an aniasis. For each characteristic or contaminant.  JINIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate are:  ENGLISH UNIT OF MEASURE — CODE METRIC UNIT OF MEASURE — CODE FOUNDS. — FILLOGRAMS. — METRIC TONS. — METRIC TON				
PA HAZARDOUS WASTE NUMBER — Enter the four-digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If sand/or the toxic contaminants of those hazardous wastes.  STIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an aniasis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste/s/. that will be handled on an aniasis. For each characteristic or contaminant.  JINIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate are:  ENGLISH UNIT OF MEASURE — CODE METRIC UNIT OF MEASURE — CODE FOUNDS. — FILLOGRAMS. — METRIC TONS. — METRIC TON				
PA HAZARDOUS WASTE NUMBER — Enter the four-digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If sand/or the toxic contaminants of those hazardous wastes.  STIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an aniasis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste/s/. that will be handled on an aniasis. For each characteristic or contaminant.  JINIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate are:  ENGLISH UNIT OF MEASURE — CODE METRIC UNIT OF MEASURE — CODE FOUNDS. — FILLOGRAMS. — METRIC TONS. — METRIC TON				
PA HAZARDOUS WASTE NUMBER — Enter the four-digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If sand/or the toxic contaminants of those hazardous wastes.  STIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an aniasis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste/s/. that will be handled on an aniasis. For each characteristic or contaminant.  JINIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate are:  ENGLISH UNIT OF MEASURE — CODE METRIC UNIT OF MEASURE — CODE FOUNDS. — FILLOGRAMS. — METRIC TONS. — METRIC TON			放金 18 64 18 4 18 4 18 18 18 18 18 18 18 18 18 18 18 18 18	
PA HAZARDOUS WASTE NUMBER — Enter the four-digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If andle hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four-digit number(s) from 40 CFR, Subpart C that describes the charactics and/or the toxic contaminants of those hazardous wastes.  STIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an aniasis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste(s) that will be handled possess that characteristic or contaminant.  INIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate are:  ENGLISH UNIT OF MEASURE CODE METRIC UNIT OF MEASURE CODE  FOUNDS.				
PA HAZARDOUS WASTE NUMBER — Enter the four—digit number from 40 CFR, Subpart D for each listed hazardous waste vou will handle. If andle hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four—digit number(s) from 40 CFR, Subpart C that describes the characterisatic or toxic contaminants of those hazardous wastes.  STIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an aniasis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non—listed waste(s)-that will be handled possess that characteristic or contaminant.  INIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate are:				
PA HAZARDOUS WASTE NUMBER — Enter the four-digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If andle hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four-digit number(s) from 40 CFR, Subpart C that describes the charactics and/or the toxic contaminants of those hazardous wastes.  STIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an aniasis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste(s) that will be handled possess that characteristic or contaminant.  INIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate are:  ENGLISH UNIT OF MEASURE CODE METRIC UNIT OF MEASURE CODE  FOUNDS.				
PA HAZARDOUS WASTE NUMBER — Enter the four—digit number from 40 CFR, Subpart D for each listed hazardous waste vou will handle. If andle hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four—digit number(s) from 40 CFR, Subpart C that describes the characterisatic or toxic contaminants of those hazardous wastes.  STIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an aniasis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non—listed waste(s)-that will be handled possess that characteristic or contaminant.  INIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate are:				
PA HAZARDOUS WASTE NUMBER — Enter the four-digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If sand/or the toxic contaminants of those hazardous wastes.  STIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an aniasis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste/s/. that will be handled on an aniasis. For each characteristic or contaminant.  JINIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate are:  ENGLISH UNIT OF MEASURE — CODE METRIC UNIT OF MEASURE — CODE FOUNDS. — FILLOGRAMS. — METRIC TONS. — METRIC TON				
PA HAZARDOUS WASTE NUMBER — Enter the four-digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If andle hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four-digit number(s) from 40 CFR, Subpart C that describes the charactics and/or the toxic contaminants of those hazardous wastes.  STIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an aniasis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste(s) that will be handled possess that characteristic or contaminant.  INIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate are:  ENGLISH UNIT OF MEASURE CODE METRIC UNIT OF MEASURE CODE  FOUNDS.				DESIGNATION OF THE PARTY OF THE
PA HAZARDOUS WASTE NUMBER — Enter the four-digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If sand/or the toxic contaminants of those hazardous wastes.  STIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an aniasis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste/s/. that will be handled on an aniasis. For each characteristic or contaminant.  JINIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate are:  ENGLISH UNIT OF MEASURE — CODE METRIC UNIT OF MEASURE — CODE FOUNDS. — FILLOGRAMS. — METRIC TONS. — METRIC TON				
PA HAZARDOUS WASTE NUMBER — Enter the four—digit number from 40 CFR, Subpart D for each listed hazardous waste vou will handle. If least hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four—digit number/s/ from 40 CFR, Subpart C that describes the charact ics and/or the toxic contaminants of those hazardous wastes.  ESTIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an analysis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non—listed waste/s/-that will be handled on an analysis. For each characteristic or contaminant.  UNIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate are:  ENGLISH UNIT OF MEASURE CODE METRIC UNIT OF MEASURE CODE  FOUNDS. — PROCESSES. — RECESSES. — PROCESSES. — For each listed hazardous waste entered in column A select the code/s/ from the list of process codes contained in ltem to indicate how the wastes: For each listed hazardous waste entered in column A select the code/s/ from the list of process codes contained in ltem to indicate how the wastes: For each characteristic or toxic contaminant. However, and/or disposed of at the facility. For non—listed hazardous wastes: For each characteristic or toxic contaminant. Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three or described shares (2) Form the list of process codes. Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three or described shares (2) Form the code of the process are provided for entering process codes. If more are needed: (1) Enter the first three or described shares (2) Form the code of the c				
PA HAZARDOUS WASTE NUMBER — Enter the four—digit number from 40 CFR, Subpart D for each listed hazardous waste vou will handle. If nandle hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four—digit number/s/ from 40 CFR, Subpart C that describes the charactics and/or the toxic contaminants of those hazardous wastes.  ESTIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an analysis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non—listed waste/s/-that will be handled on an analysis. For each characteristic or contaminant.  JNIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate are:  ENGLISH UNIT OF MEASURE CODE METRIC UNIT OF MEASURE CODE  FOUNDS. — PROCESSES. — Records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking account the appropriate density or specific gravity of the waste.  PROCESSES. — For listed hazardous waste: For each listed hazardous waste entered in column A select the code/s/ from the list of process codes contained in Item to indicate how the wastes: For each characteristic or toxic contaminant.  Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three or described shared on wastes that post that characteristic or toxic contaminant.  Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three or described shared to the space of the code of the process are provided for entering process codes. If more are needed: (1) Enter the first three or described shared to the code of t	。 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1			
PA HAZARDOUS WASTE NUMBER — Enter the four-digit number from 40 CFR, Subpart D for each listed hazardous waste vou will handle. If landle hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four-digit number(s) from 40 CFR, Subpart C that describes the characterist ices and/or the toxic contaminants of those hazardous wastes.  STIMATED ANNUAL QUANTITY — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an animal pass. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste(s)-that will be handled possess that characteristic or contaminant.  JINIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate are:  ENGLISH UNIT OF MEASURE CODE METRIC UNIT OF MEASURE CODE  FOUNDS. — PROCESSES. — RECESSES. — PROCESS CODES:  For listed hazardous waste: For each listed hazardous waste entered in column A select the code(s) from the list of process codes contained in Item to indicate how the wastes: For each characteristic or toxic contaminant. How the processes that will be used to store, treat, and/or dispose of all the non-listed hazardous wastes: For each characteristic or toxic contaminant. Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three or described shows asses that wastes that possible the contaminant.	DESCRIPTION OF HAZARDONG WASHINGTON	THE SECTION OF SECURE	Party Mark and Control of the Control of	County and and the second
UNIT OF MEASURE — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate density or specific gravity of the waste.  PROCESSES  I. PROCESS CODES: For listed hazardous waste: For each listed hazardous waste entered in column A select the code(s) from the list of process codes contained in Item III to indicate all the processes that will be used to store, treat, and/or dispose of all the non—listed hazardous wastes that post that characteristic or toxic contaminant.  Note: Four spaces are provided for entering process codes.	EPA HAZARDOUS WASTE NUMBER - Enter the f	our-digit number from	AO CER Subpart D for each listed bazardou	- waste way will bandle If
ENGLISH UNIT OF MEASURE  POUNDS.  TONS.  TON	PA HAZARDOUS WASTE NUMBER — Enter the franche hazardous wastes which are not listed in 40 Clics and/or the toxic contaminants of those hazardous was a strict and the second seco	wastes.	te four-digit number(s) from 40 CFR, Subpart	C that describes the characte
For listed hazardous waste: For each listed hazardous waste entered in column A select the code/s/ from the list of process codes contained in Item to indicate how the wastes: For each characteristic or toxic contaminant entered in column A, select the code/s/ from the list of process codes contained in Item that characteristic or toxic contaminant entered in column A, select the code/s/ from the list of process codes contained in Item that characteristic or toxic contaminant entered in column A, select the code/s/ from the list of process codes contained in Item III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed hazardous wastes that post that characteristic or toxic contaminant.  Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three or described character (2) Enter (20) From (2) Enter (2	PA HAZARDOUS WASTE NUMBER — Enter the financial hazardous wastes which are not listed in 40 Clics and/or the toxic contaminants of those hazardous wastes and/or the toxic contaminants of those hazardous wastes. For each characteristic or toxic contaminant entwhich possess that characteristic or contaminant.  JNIT OF MEASURE — For each quantity entered in	wastes.  ed waste entered in column A estimates.	umn A estimate the quantity of that waste that at the total annual quantity of all the non-list	C that describes the charact it will be handled on an ani ed waste(s)-that will be hand
facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking count the appropriate density or specific gravity of the waste.  ROCESSES  PROCESS CODES: For listed hazardous waste: For each listed hazardous waste entered in column A select the code(s) from the list of process codes contained in Item to indicate how the waste will be stored, treated, and/or disposed of at the facility.  For non-listed hazardous wastes: For each characteristic or toxic contaminant entered in column A, select the code(s) from the list of process contained in Item III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed hazardous wastes that post that characteristic or toxic contaminant.  Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three or described character (2) Enter (10) for the list of process codes.	PA HAZARDOUS WASTE NUMBER — Enter the financial hazardous wastes which are not listed in 40 Clics and/or the toxic contaminants of those hazardous wastes and/or the toxic contaminants of those hazardous wastes. For each characteristic or toxic contaminant entwhich possess that characteristic or contaminant.  UNIT OF MEASURE — For each quantity entered in odes are:	wastes.  ed waste entered in column A estimates.	umn A estimate the quantity of that waste that at the total annual quantity of all the non-list	C that describes the charact it will be handled on an ani ed waste(s)-that will be hand
facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking count the appropriate density or specific gravity of the waste.  ROCESSES PROCESS CODES: For listed hazardous waste: For each listed hazardous waste entered in column A select the code(s) from the list of process codes contained in Item to indicate how the waste will be stored, treated, and/or disposed of at the facility.  For non-listed hazardous wastes: For each characteristic or toxic contaminant entered in column A, select the code(s) from the list of process contained in Item III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed hazardous wastes that post that characteristic or toxic contaminant.  Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three or described above (2) Enter the code(s).	PA HAZARDOUS WASTE NUMBER — Enter the fandle hazardous wastes which are not listed in 40 Clics and/or the toxic contaminants of those hazardous wastes which are not listed in 40 Clics and/or the toxic contaminants of those hazardous wastes. For each characteristic or toxic contaminant entwhich possess that characteristic or contaminant.  UNIT OF MEASURE — For each quantity entered in odes are:  ENGLISH UNIT OF MEASURE	ed waste entered in column A estimate column B enter the un	umn A estimate the quantity of that waste that ate the total annual quantity of all the non-list art of measure code. Units of measure which materials with the measure which with the measure which with the measure which with the measure which with the measure with the measure which with the measure which with the measure with the measure with the measure with the measure which with the measure with the measu	c that describes the charact will be handled on an anied waste(s)-that will be handled to be used and the appropriate to the control of the c
PROCESSES PROCESS CODES: For listed hazardous waste: For each listed hazardous waste entered in column A select the code(s) from the list of process codes contained in Item to indicate how the waste will be stored, treated, and/or disposed of at the facility. For non-listed hazardous wastes: For each characteristic or toxic contaminant entered in column A, select the code(s) from the list of process of contained in Item III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed hazardous wastes that post that characteristic or toxic contaminant.  Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first through december (2) Enter 100001 in	PA HAZARDOUS WASTE NUMBER — Enter the financial hazardous wastes which are not listed in 40 Clics and/or the toxic contaminants of those hazardous wastes and/or the toxic contaminants of those hazardous wastes.  STIMATED ANNUAL QUANTITY — For each lister lasts. For each characteristic or toxic contaminant entwice possess that characteristic or contaminant.  JUNIT OF MEASURE — For each quantity entered in odes are:  ENGLISH UNIT OF MEASURE  POUNDS.	wastes.  ed waste entered in column A estimate column B enter the un	umn A estimate the quantity of that waste that ate the total annual quantity of all the non-list are of measure code. Units of measure which materials with the materials of the measure which materials of the measure	t will be handled on an and ed waste(s)-that will be handled used and the appropriate the used and the appropriate that will be used to the appropriate that will be used
PROCESS CODES: For listed hazardous waste: For each listed hazardous waste entered in column A select the code(s) from the list of process codes contained in Item to indicate how the waste will be stored, treated, and/or disposed of at the facility.  For non-listed hazardous wastes: For each characteristic or toxic contaminant entered in column A, select the code(s) from the list of process contained in Item III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed hazardous wastes that post that characteristic or toxic contaminant.  Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three or described character (2) Enter those in the code (3).	PA HAZARDOUS WASTE NUMBER — Enter the frandle hazardous wastes which are not listed in 40 Clics and/or the toxic contaminants of those hazardous wastes which are not listed in 40 Clics and/or the toxic contaminants of those hazardous wastes and the toxic contaminant entered in passes that characteristic or contaminant.  JNIT OF MEASURE — For each quantity entered in codes are:  ENGLISH UNIT OF MEASURE POUNDS	ed waste entered in column A estimatered in column B enter the un	umn A estimate the quantity of that waste that ate the total annual quantity of all the non-list are the total annual quantity of measure which make the total annual quantity of all the non-list annual quantity of all t	c that describes the charact will be handled on an an ed waste(s)-that will be handled to the appropriate that we will be used and the appropriate that will be used and the appropriate that will be used and the appropriate that we will be used and the appropriate that will be used to be
For listed hazardous waste: For each listed hazardous waste entered in column A select the code(s) from the list of process codes contained in Item to indicate how the waste will be stored, treated, and/or disposed of at the facility.  For non-listed hazardous wastes: For each characteristic or toxic containant entered in column A, select the code(s) from the list of process contained in Item III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed hazardous wastes that post that characteristic or toxic containant.  Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three or described character (2) Enter (2) Enter (3) Enter (4) Enter (4) Enter (5) Enter (5) Enter (6) Enter (6) Enter (7) Ent	EPA HAZARDOUS WASTE NUMBER — Enter the frandle hazardous wastes which are not listed in 40 Clics and/or the toxic contaminants of those hazardous wastes and/or the toxic contaminants of those hazardous wastes and/or the toxic contaminant of the passis. For each characteristic or toxic contaminant entwhich possess that characteristic or contaminant.  UNIT OF MEASURE — For each quantity entered in codes are:  ENGLISH UNIT OF MEASURE POUNDS	ed waste entered in column A estimatered in column B enter the un	umn A estimate the quantity of that waste that ate the total annual quantity of all the non-list are the total annual quantity of measure which make the total annual quantity of all the non-list annual quantity of all t	t will be handled on an and ed waste(s)-that will be handled on an and ed waste(s)-that will be handled to be used and the appropriate to be used and the appropriate to be used.
For non-listed hazardous wastes: For each characteristic or toxic contaminant entered in column A, select the code/s/ from the list of process or contained in Item III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed hazardous wastes that post that characteristic or toxic contaminant.  Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three or described characteristic described characteristic or toxic contaminant.	PA HAZARDOUS WASTE NUMBER — Enter the francile hazardous wastes which are not listed in 40 Clics and/or the toxic contaminants of those hazardous wastes which are not listed in 40 Clics and/or the toxic contaminants of those hazardous wastes and the toxic contaminant entered in passess that characteristic or contaminant.  JNIT OF MEASURE — For each quantity entered in codes are:  ENGLISH UNIT OF MEASURE POUNDS	ed waste entered in column A estimatered in column B enter the un	umn A estimate the quantity of that waste that ate the total annual quantity of all the non-list are the total annual quantity of measure which make the total annual quantity of all the non-list annual quantity of all t	t will be handled on an and ed waste(s)-that will be handled on an and ed waste(s)-that will be handled to be used and the appropriate to be used and the appropriate to be used.
that characteristic or toxic contaminant.  Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first through the described characteristic or described characteristic or toxic contaminant.	PA HAZARDOUS WASTE NUMBER — Enter the frandle hazardous wastes which are not listed in 40 Clics and/or the toxic contaminants of those hazardous wastes.  STIMATED ANNUAL QUANTITY — For each listed passis. For each characteristic or toxic contaminant entwhich possess that characteristic or contaminant.  JNIT OF MEASURE — For each quantity entered in codes are:  ENGLISH UNIT OF MEASURE POUNDS	column B enter the uncolumn B	umn A estimate the quantity of that waste that ate the total annual quantity of all the non-list of measure code. Units of measure which make the code. Units of measure which make the code. Units of measure which make the code.  METRIC UNIT OF MEASURE KILOGRAMS	C that describes the charact it will be handled on an an ed waste(s)-that will be handled to the appropriate to the control of
Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three as described change (2) Four 1000%;	PA HAZARDOUS WASTE NUMBER — Enter the frandle hazardous wastes which are not listed in 40 Clics and/or the toxic contaminants of those hazardous wastes. STIMATED ANNUAL QUANTITY — For each lister passis. For each characteristic or toxic contaminant entwhich possess that characteristic or contaminant.  UNIT OF MEASURE — For each quantity entered in codes are:  ENGLISH UNIT OF MEASURE POUNDS	column B enter the uncolumn B	umn A estimate the quantity of that waste that ate the total annual quantity of all the non-list of measure code. Units of measure which make the total annual quantity of all the non-list of measure code. Units of measure which make the code annual quantity of all the non-list of measure which make the code annual quantity of the measure must be converted into one of the requirements of the code annual quantity.	C that describes the charact it will be handled on an an ed waste(s)-that will be handled to be used and the appropriate to be used to b
	PA HAZARDOUS WASTE NUMBER — Enter the frandle hazardous wastes which are not listed in 40 Clics and/or the toxic contaminants of those hazardous wastes. STIMATED ANNUAL QUANTITY — For each listed basis. For each characteristic or toxic contaminant entwhich possess that characteristic or contaminant.  JNIT OF MEASURE — For each quantity entered in codes are:  ENGLISH UNIT OF MEASURE POUNDS. TONS.  f facility records use any other unit of measure for occount the appropriate density or specific gravity of the ROCESSES. PROCESS CODES: For listed hazardous wastes: For each listed hazardous indicate how the waste will be stored, treated, an For non—listed hazardous wastes: For each charactentained in Item III to indicate all the processes	column B enter the uncertainty, the units of materials, the waste entered in column A estimated in the units of materials.	umn A estimate the quantity of that waste that ate the total annual quantity of all the non-list ate the total annual quantity of all the non-list ate the total annual quantity of all the non-list ate the total annual quantity of all the non-list ate the total annual quantity of all the non-list ate the total annual quantity of all the non-list ate the code (s) from the list of profacility.	t will be handled on an anied waste(s)-that will be handled on an anied waste(s)-that will be handled to be used and the appropriate to be used
	EPA HAZARDOUS WASTE NUMBER — Enter the frandle hazardous wastes which are not listed in 40 Claics and/or the toxic contaminants of those hazardous wastes and/or the toxic contaminants of those hazardous wastes. For each characteristic or toxic contaminant entwhich possess that characteristic or contaminant.  UNIT OF MEASURE — For each quantity entered in codes are:  ENGLISH UNIT OF MEASURE  POUNDS	CODE  CODE  COURT  COUR	wmn A estimate the quantity of that waste that ate the total annual quantity of all the non-list of measure code. Units of measure which make the total annual quantity of all the non-list of measure code. Units of measure which make the code. Units of measure which make the code. Units of measure which make the code. We the code of the requirement of the code of the code. The code of the	t will be handled on an anied waste(s)-that will be handled on an anied waste(s)-that will be handled to be used and the approprime to be used

that will be used, describe the process in the space provided on the form.

NOTE: HAZARDOUS WASTES DESCRIBED BY MORE THAN ONE EPA HAZARDOUS WASTE NUMBER - Hazardous wastes that can be described by more than one EPA Hazardous Waste Number shall be described on the form as follows:

- 1. Select one of the EPA Hazardous Waste Numbers and enter it in column A. On the same line complete columns B,C, and D by estimating the total annual
- quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste.

  2. In column A of the next line enter the other EPA Hazardous Waste Number that can be used to describe the waste. In column D(2) on that line enter "included with above" and make no other entries on that line.
- 3. Repeat step 2 for each other EPA Hazardous Waste Number that can be used to describe the hazardous waste.

EXAMPLE FOR COMPLETING ITEM IV (shown in line numbers X-1, X-2, X-3, and X-4 below) — A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tanning and finishing operation. In addition, the facility will treat and dispose of three non-listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 100 pounds per year of that waste. Treatment will be in an incinerator and disposal will be in a landfill.

	A. EPA HAZARD. B. ESTIMATED ANNUAL O WASTENO QUANTITY OF WASTE			HAZARD. B. ESTIMATED ANNUAL WASTENO QUANTITY OF WASTE				AZARD. B. ESTIMATED ANNUAL ASTENO QUANTITY OF WASTE				D. PROCESSES  1. PROCESS CODES  2. PROCESS DESCRIPTION										
JZ	(ent	er	ode	"		(enter		4	HAR!	16.4		(ent	er)	A PORT	(if a code is not entered in D(1))							
X-1	K	0	5	4	900	P		T	0 3	Z	8	0										
X-2	D	0	0	2	400	P		T	0 3	3 L	8	0	1 1	11								
X-3	$D \mid c$	0	0	1	100	P		T	0 3	Z	8	0										
X-4	D	0	0	2						1	T			1.51	included with above							
FRA F		7-		7.	221		_	-	_	_	-											

Continued from page 2. NOTE: Photocopy this page before completing if you have more than 26 wastes to list. Form Approved OMB No. 158-S80004 FOR OFFICIAL USE ONLY EPA I.D. NUMBER (enter from page 1) 8 DUP W DUP W IV. DESCRIPTION OF HAZARDOUS WASTES (continued) C. UNIT OF MEA-SURE (enter code) D. PROCESSES A. EPA HAZARD. WASTE NO (enter code) B. ESTIMATED ANNUAL QUANTITY OF WASTE 1. PROCESS CODES (enter) 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) NO. 29 27 - 29 27 36 Aqueous leachate 1 \*70.000 DO 0 190 T S 04 5 02 Non-Aqueous leachate 3 5 8 9 10 11 12 13 14 15 16 17 18 19 20 \*No hazardous 21 waste code is available for leachate from 23 a hazardous waste landfill. 24

25

26

Continued from the front.											
IV. DESCRIPTION OF HAZARDOUS WASTL con	tinued)	The state of the	The state of	4	South			u.		0 4	Green.
FE. USE THIS SPACE TO LIST ADDITIONAL PROC		S FROM IT	EM D(1) O	N PAG	E 3.				17.00		
A STATE OF THE STA	TELEPIS .		Società Ser	1	LES ARLES			SAA			F 68.
		S STATE OF							40.5		
				Fig. 3						. 10	
						1941 20			93.5		
				V							
		145 sn							3.7		
						15 500					
							LU K				
									133		
								STORY.		1016	
EPA I.D. NO. (enter from page 1)											
F N YD 0 00 8 31 6 44 6											
V. FACILITY DRAWING	CALL STATE		SPECIAL CONTRACTOR	900 8 80	Affe	A: 13. T					
All existing facilities must include in the space provided on p	age 5 a scale	drawing of th	e facility (see	e instruc	tions for mor	e detail).		-	الم المنافقة		
VI. PHOTOGRAPHS		1000000	200	A ALA		SELE.	100		3.4	100	A COLUMN
All existing facilities must include photographs (aeria	l or ground	-level   that	clearly del	ineate a	Il existing s	tructure	s: exi	ting	storac	e.	
treatment and disposal areas; and sites of future store											
VII. FACILITY GEOGRAPHIC LOCATION	2							33.1	ER 91375	* ***	
LATITUDE (degrees, minutes, & seconds)				LONGIT	TUDE (degree	s, minute	rs, & sc	cond	s)	نوتلشي	
4 3 0 7 5 4	districts	9-862/ 54000	1134 (a. 25) (a. 1	ALBERT.	07 0	ah II.	JI				cells:
4 3 U / D 4 52 54 57 58 59 21		生態 新疆		300	0/ 9	02 0	<u> </u>				
VIII. FACILITY OWNER					2.25.6.2	200	3 - 10 (*) 21 - 10 (*)	1			
A. If the facility owner is also the facility operator as li	sted in Section	n VIII on Fo	rm 1 "Gener	rai Inform	mation". plac	e an "X"	in the	box	to the	left ar	nd
skip to Section IX below.		esta la s	ici canolii		estro serv	to the fact					
B. If the facility owner is not the facility operator as lis	ted in Costin	- Will on Fo	m 1 somele	to the f	ollowing item						
B. If the facility owner is not the facility operator as its	stea in Sectio	n vili on Foi	m 1, comple	te the n	onowing item		9 14				
1. NAME OF FACIL	ITY'S LEGA	LOWNER	er Mur <sub>ie</sub>			2.	PHON	E NO	. (area	code	& no.)
E	The state of the s	News Cha			186842						
11 116	peranders o	the same of		THURST.	a comence	33 36	- 50	59 -	- 51	62	1 1,
3. STREET OR P.O. BOX	经产品 化有金	12 Sept. 40	CITY OR TO	OWN	17 -46	5. ST.		6.	ZIP CC	DDE	
· F	c C		AND MICH.	Pron set	rigid ka		400				
12 16 -	G				40	41 42		<del>,</del> —		5	41.21
IX. OWNER CERTIFICATION						政府等					
I certify under penalty of law that I have personally e	examined ar	nd am famil	iar with the	inform	ation subm	itted in	this a	nd al	attac	hed	
documents, and that based on my inquiry of those in	dividuals in	nmediately i	responsible	for obt	aining the i	nformat	ion, I	belie	ve tha	it the	
submitted information is true, accurate, and complete	e. I am awa	re that there	e are signifi	cant pe	nalties for s	ubmittii	ng fals	e inf	ormat	ion,	
including the possibility of fine and imprisonment.				Execution.	MINE SEL	rjeger veril				1778	42.32
A. NAME (print or type)	B. SIGNAT	URE	Section 1991	La dal	Sharpark.	C. DA	TE SIG	NED	The said		
Dr. Norman Alpert	11		001	1		1	d.	7	,99	7	
Vice-President, Occidental Ch	em. //o	rman	uep	evi	ALC: IN NO	0	CN-	1,	110	>	de de la
X. OPERATOR CERTIFICATION COLD		7						Wet - 2			
I certify under penalty of law that I have personally e	examined a	nd am famil	iar with the	inform	nation subm	itted in	this a	nd al	l attac	hed	
documents, and that based on my inquiry of those in	dividuals in	nmediately	responsible	for obt	aining the i	nformat	ion, I	belie	ve tha	t the	
submitted information is true, accurate, and complet	e. I am awa	re that there	e are signifi	icant pe	nalties for s	ubmittii	ng fals	e inf	ormat.	ion,	
including the possibility of fine and imprisonment.					yet this			17 7	Q S		
A. NAME (print or type)	B. SIGNAT	URE	100	916.00	Market.	C. DA	TE SIC	NED			
		and to the				200		7			7 11
					17 A 44 A	P. S. B. P.			45 14	1	
										FON	

REGIONAL HEAPING OLERK

OCT IN 11 CO MM '83
ENVIRONMENTAL PROTECTION
NEW YERK, N.Y. 10007

## NYD000831644



## \*CORRESPONDENCE CONTROL OFFICE (CCO)

(SEE REVERSE FOR IMPORTANT INFORMATION)

1 At	×	( ) BARRACK	( )	MARSHALL
111 portile.		( ) BONCHONSKY	( )	METZGER
that I so to		( ) CLEVENGER	( )	SIMON
145		( ) GEISELMAN		LLEWELLYN
AUT		( ) HOLM	(6)	Sibrigi
will be the	( )	Please prepare a reply Administrator's signatu		the Regional
90 000	( )	Please prepare a reply Regional Administrator		
m.	w	Please prepare a direct	: re	ply.
		Please reply by telephore pink control slip to Control slip to Control and day reply DUE NOT LATER THE	CO ar	nd indicate
		Please include pink con extra copy of reply for control office. (Do no attachments with CCO co	troi	respondence nclude
	REM	ARKS:	····	
			<del></del>	. /